# Getting to Know Your Shadowpad






### Shadowpad Includes:

- 1 light board
- 1 power adapter
- 4 Corner Brackets






## Getting Started:

and the second s

- Place your Shadowpad on a flat and level surface.
- Plug in the Power Cord to the Shadowpad and outlet, turn on by pressing the power button once.
- Set camera/phone settings: High Resolution, and flash off
- Place Corner Brackets as a reference for the size of the tool drawer/tray

#### PLEASE NOTE: Final images should be greater than 1MB




# Tips for Taking your pictures:


- **Space** tools a minimum of 3/8" from each other and edge of tray
- Center tools on the middle of the shadowpad
- Avoid placing tall/long tools around the edges of tray
- Trays with tools/parts taller than 3" replace with paper cutout of shape
- Do NOT zoom in on camera, hold phone as flat as possible
- Take photo from a raised level entire outside border of should be present in photo

# PLEASE NOTE: Final images should be greater than 1MB






# than 1MB



## **Unacceptable Photos:**



#### PLEASE NOTE: Final images should be greater than 1MB





# Filling out the Tool Tray Log (TTL):

And the state of t

- All fields are required, including: Company Name, Contact, Phone Number, etc.
- The TTL should be renamed to a unique identifier such as John Doe's Tool Trays
- Picture Name on TTL must match file names of pictures
- Select material type based on your needs, tool control, ESD or Clean Room safe.
- When choosing your tray dimensions, make sure you consider anything protruding from the drawer
- Add unique specifications or requests under Comments
- Thumb bars (relief cuts to remove tools) are recommended and are no additional charge

DATE ALL FIELDS ARE REQUIRED				Tool Tray Log									***PLEASE EMAIL THIS COMPLETED FORM DIRECTLY TO YOUR REP AT PLASTEEL. IF YOU ARE UNSURE OF WHO YOUR REP IS, PLEASE SEND THIS TO FOD@PLASTEELAZ.COM, OR CONTACT US AT 480-491-8100			
Company Name: Company INC			Contact Name:			John Doe				Purchase Order Number:		nber:	: 00-000-0000			
Address:		123 N Street		Contact Phone:		000-000-0000		Ext.	0	Comments:		Do not add thumbars on wrenches		on wrenches		
City, State, Zip: Tempe, AZ 00000				Contact Email:		John.Doe@companyinc.com										
#		Picture Name	Material Type		Length	Tray Dim Width	nensions Top Height	Btm Height	Со Тор	lor Btm	Quantity Of Each Layout	Thumbbars (Y or N)	Labels (Y or N)	Additional Add-Ons/Comments		
1	John Does Too	lohn Does Tool Tray.img			23."	15."	.5"	.25"	BLACK	RED	8	YES	NO			
2	John Does Tool Tray 2.img		Stata-DENE		20."	13.5"	.5"	.25"	BLACK	BLUE	2	YES	YES			
3	3															
4	4															
5																
Tool Tray Log     Engraving Log <ul> <li></li></ul>																

# Filling out the

- Labels are OPTI •
- List labels unde •

- QTY: enter tota •
- 20 Character lim •

Filling out the Engr			gotfod?			
Labels are OPTIONAL, placard List labels under "Label Entry" QTY: enter <b>total</b> amount being 20 Character limit per row, 2 ro	Side grind location Center Drill fixture nose grind location nose grind heads	plate plate tock	And A real of a summa manual			
TOTAL: 7	Line 1	Line 2	Qty	Line 1	diamond roll	Qty
20 Characters MAX Per Row 2 Rows MAX Per Label If cell turns red, reduce characters or use Line 2	Screwdrivers 8 mm Socket 10 mm Socket Wrench Allen Keys	Line 2	2 2 2 2		Line 2	

÷

- -

# Submitting order:

- Submit pictures and completed Tool Tray Log to your PEI rep
- Images need to be submitted as full-size attachments, minimum 1MB
- Plasteel can provide a secure link to upload photos to upon request

### Contact us: 480-491-8100

info@plasteelaz.com

# Thank You for Purchasing Your Shadowpad

Submit Tool Tray Log and Photos via E-mail

www.gotfod.com FOD@plasteelaz.com 480-491-8100



