Getting to Know Your Smart-box



Smart-box Includes:

The state of the s

- 1 Power Cable
- 4 Corner Brackets
- 3 pc Canopy
- 1 Smart-box







GettingStarted:

- Assemble canopy
- Plug in the Power Cord to the Lightbox and outlet, light with automatically turn on.
- Set camera settings: **High Resolution**, and flash set to **off**
- Place Corner Brackets as a reference for the size of the tool drawer/tray
- Space tools a minimum of 3/8" from each other and edge of tray
- Avoid placing tall/long tools around the edges of tray
- Trays with tools/parts taller than 3" should have a paper cutout in it's place
- Do NOT zoom in on camera
- Red border should be visible in images (if applicable)
- Final images should be greater than 1MB



Filling out the Tool Tray Log (TTL):



- All fields are required, including: Company Name, Contact, Phone Number, etc.
- The TTL should be renamed to a unique identifier such as John Does Tool Trays
- Picture Name on TTL must match Image Names of pictures taken of tools on Smart-box
- Select your material type based on your needs, tool control, ESD or Clean Room safe
- When choosing your tray dimensions, make sure you consider anything protruding from the drawer
- Be sure to add unique specifications or requests under Comments
- Please submit Tool Tray logs and pictures to your FOD Rep
- Thumb bars are recommended and are no additional charge

DATE ALL FIELDS ARE REQUIRED				Tool Tray Log									***PLEASE EMAIL THIS COMPLETED FORM DIRECTLY TO YOUR REP AT PLASTEEL. IF YOU ARE UNSURE OF WHO YOUR REP IS, PLEASE SEND THIS TO FOD@PLASTEELAZ.COM, OR CONTACT US AT 480-491-8100		
Company Name: Company INC			Contact Na		t Name:					Purchase Order Number:			00-000-0000		
Address:		123 N Street		Contact Phone:		000-000-0000		Ext.	0	Comments:		Do not add thumbars on wrenches		on wrenches	
City, State, Zip: Tempe, AZ 00000			Contact Em		t Email:	John.Doe@companyinc.com									
#		Picture Name		Material Type		Tray Dimensions Width Top Height Bi		Btm Height	Color Top Btm		Quantity Of Each Layout	Thumbbars (Y or N)	Labels (Y or N)	Additional Add-Ons/Comments	
1	John Does Tool Tray.img		Stata-DENE		23."	15."	.5"	.25"	BLACK	RED	8	YES	NO		
2	John Does Tool Tray 2.img		Stata-DENE		20."	13.5"	.5"	.25"	BLACK	BLUE	2	YES	YES		
3															
4	4														
5		Fray Log Engraving Log (+													

Filling out the Engraving Log:



At the bottom of the Tool Tray log you will find an additional tab called Engraving Log. Click on that to open it up

- Under Label Entry list labels being used on all trays entered on TTL
- QTY enter total amount of each label being used on all trays

TOTAL: 8			
	Label Entry	Qty	
	8 mm Socket	1	
	10mm Socket	1	
	11mm Socket	1	
	13mm Socket	1	
	Wrench	4	
Tool Tray Log Engraving Log +			: 4

Thank You for Purchasing Your Smart-box

www.gotfod.com FOD@plasteelaz.com 480-491-8100



